



“ DG press ServiceS is a company with the experience, know-how and the innovative drive of Drent Goebel specialists to be At Your Service ”

VSOP 520 and 850 software update to prevent speed error

DGpS can take care of a software update for your VSOP 520 and 850 print units to prevent speed error in standstill.

An issue can occur when the VSOP print units are in standalone and a job change has to be done during standstill of the press. It is possible that the machine get into a sercos speed error during changing of the sleeves.

The following error can be shown: Speed error 11 or speed error 12. This give a sercos error in the whole machine. Other print units which are in washing mode or going into change mode or to production mode, are stopping directly.

Remark: Speed sensors on gearboxes from the plate, blanket and impression should be M12 sensors.

Contact DGpS

- **Reduces your down-time**
- **Quicker job-changes**
- **Less time wasted on solving speed errors**

