

Modification; spring return oscilator gear for Vision/VSOP


DgpS can supply a modification kit to improve the printing quality.

Streaks in printing are sometimes unavoidable while printing with an Vision or "early" VSOP. These streaks are often the result of the oscilating roller giving pulses to the ink train. The spring return oscillator gear will smoothen these pulses considerable which result in less streaks on the print. Thus creating a larger window of operating with less water

The basics for this modification consist of a spring mounted in the gear assembly.

- Improved printing quality.
- Increased printing speeds
- Increased productivity of your printing process







Hallseweg 21 6964 AJ Hall P.O. Box 70, 6960 AB Eerbeek The Netherlands

Phone: +31 313 (0) 671911 Fax:+31 313 (0) 671191 Info@dgpressservices.com www.dgpressservices.com