

“ DG press ServiceS *bv* is a company with the experience, know-how and the innovative drive of Drent Goebel specialists to be At Your Service ”

Modification; register rings for VSOP

DgpS can supply a modification kit to solve the issue of broken register pins for sleeve positioning.

The increased weight of the new generation sleeves leads to an increased load on the register pins on the sleeve mandrell.

The existing pins on the Drent VSOP presses can damage. Repair of broken register pins is time consuming and will require special skills.

By mounting of a special designed register ring and register plates the system is more robust. Eventual replacement of broken plates is easy, quick and can be done without special skills.

- **Reduces downtime**
- **Reduces unplanned machine stops by broken pins.**
- **Less operator care needed by inserting and position of sleeves.**
- **Increased reliability and robustness of your printing process**

